

These flashes summarise key safety matters and incidents, allowing wider dissemination of lessons learned from them. The information below has been provided in good faith by members and should be reviewed individually by recipients, who will determine its relevance to their own operations.

The effectiveness of the IMCA safety flash system depends on receiving reports from members in order to pass on information and avoid repeat incidents. Please consider adding the IMCA secretariat (imca@imca-int.com) to your internal distribution list for safety alerts and/or manually submitting information on specific incidents you consider may be relevant. All information will be anonymised or sanitised, as appropriate.

A number of other organisations issue safety flashes and similar documents which may be of interest to IMCA members. Where these are particularly relevant, these may be summarised or highlighted here. Links to known relevant websites are provided at www.imca-int.com/links. Additional links should be submitted to webmaster@imca-int.com

I Parting of Slings Causing Fall of Heavy Object onto Seabed

A diving support vessel was installing a 24 tonne metallic cover onto a subsea valve. When this large object was deployed over the side of the vessel into the water, the four 15 tonne round slings used in the rigging arrangement parted and the object fell into the seabed. There were no injuries or damage to equipment or seabed infrastructure as, in accordance with the company's procedures, the lift was made over a seabed area free of any field infrastructure.



Investigation revealed that the four round slings obtained from a local supplier had been modified incorrectly and without due authorisation from the original manufacturer.

- ◆ Close examination of the slings revealed that the fibre had been cut and re-spliced using numerous knots, hidden under the protective fabric (this could not have been spotted without dismantling the sling)
- ◆ Whereas 6 metre (working length) slings had been procured from the local supplier, the manufacturer advised that the serial number on the round slings actually corresponded to 12 metre (working length) round slings. The manufacturer also advised that it did not fabricate 6 m (working length) round slings of 15 tonne SWL
- ◆ There was no manufacturer certificate for the slings available from the supplier
- ◆ The blue label showing SWL was stitched to the sling, when it normally should slide around it.



The company noted the following actions:

- ◆ Rigging equipment shall in future only be procured from approved and recognised suppliers
- ◆ Rigging materials are to be always subject to testing and inspection as required by the applicable international standards and company rules
- ◆ Exceptions to the above should be subject to a rigorous and thoroughly documented management of change process covering all aspects of the rigging operation.

2 Warning Regarding Imenco Minilatch – ROV Fell Onto Deck

IMCA has received the attached safety alert regarding the Imenco Minilatch following an incident whereby an ROV fell from its launch and retrieval latch onto the deck of the support vessel.