

IMCA Safety Flash 29/19

December 2019

These flashes summarise key safety matters and incidents, allowing wider dissemination of lessons learnt from them. The information below has been provided in good faith by members and should be reviewed individually by recipients, who will determine its relevance to their own operations.

The effectiveness of the IMCA safety flash system depends on receiving reports from members in order to pass on information and avoid repeat incidents. Please consider adding the IMCA secretariat (imca@imca-int.com) to your internal distribution list for safety alerts and/or manually submitting information on specific incidents you consider may be relevant. All information will be anonymised or sanitised, as appropriate.

A number of other organisations issue safety flashes and similar documents which may be of interest to IMCA members. Where these are particularly relevant, these may be summarised or highlighted here. Links to known relevant websites are provided at www.imca-int.com/links Additional links should be submitted to info@imca-int.com

Any actions, lessons learnt, recommendations and suggestions in IMCA safety flashes are generated by the submitting organisation. IMCA safety flashes provide, in good faith, safety information for the benefit of members and do not necessarily constitute IMCA guidance, nor represent the official view of the Association or its members.

Important Safety Notice to Users of Certain Crosby Shackle Products

Crosby has prepared an Important Safety Notice for some specific Crosby 7/8" 6.5t shackles. They have reached out to their customers with a communication and have asked that the following information included on the IMCA Safety Flash webpage.



IMPORTANT SAFETY NOTICE

USERS OF THE BELOW CROSBY PRODUCT:

1019542 7/8" 6.50t S-2130 Shackle 1019533 7/8" 6.50t G-2130 Shackle 1018151 7/8" 6.50t G-213 Shackle 1018160 7/8" 6.50t S-213 Shackle 1018516 7/8" 6.50t G-209 Shackle 1018525 7/8" 6.50t S-209 Shackle 1262031 7/8" 6.50t G-2130OC Shackle

With Production Identification Codes (PIC) 5VJ as located on the shackle bow

PLEASE CAREFULLY REVIEW AND ACT UPON THE FOLLOWING INSTRUCTIONS.

November 18, 2019

Dear Valued User of Crosby Products:

THE CROSBY GROUP has determined the above listed shackles may have a condition that can reduce the ultimate load capacity from the published catalog values. The shackle bow may have a previously undetected defect, and continued use may result in loss of load, property damage, severe injury, or death.

By use of the Production Identification Code (PIC) symbols appearing on the product, we have determined the 7/8" 6.5t shackles with PIC 5VJ shown on the bow may have this condition. **See image showing the position of the PIC on the bow.** No other sizes or PICs are part of this Important Safety Notice.



We are requesting you identify all such 7/8" 6.5t shackles with PIC 5VJ, remove from service, and arrange for return and replacement. To return these products, please contact your Crosby Distributor. For more information concerning this Important Safety Notice, contact Technical Support at 1-800-772-1500.

Please inform your customer(s) of this Important Safety Notice, or if you know of other users of the 7/8" 6.5t shackles, please pass this notice on to that user, company, or firm.

We regret the inconvenience this may cause you and your organization, and thank you for your cooperation. We are committed to providing you with the absolute best in Crosby quality.

Sincerely,

THE CROSBY GROUP